

TDEC - Division of Water Resources Nashville Field Office

ICIS NPDES Facilities Inspection Report

Facility Data															
NPDES I	SID: TNR149909 Facility Site Name Terrabrooke Development														
Ado				Addr	ess [
Permit Eff. Date: 05/18/2015			Peri	mit Exp D	ate:	SIC Co					de:				
					Con	pliance Monitoring Information									
Compliance Monitoring Activity Name Stormwater Cor						struction Non-Sampling									
* If Bio Monitoring						s selected above, select the method used:									
Compliance Monitoring Activity Evaluation					on										
Compliance Monitoring Dates/Times									S						
Entry Da	Entry Date/Time (mm/dd/yyyy hh:mm): 03/02/2017 11:					5 AM Exit Date/Time (mm/dd/yyyy hh:mm): 03/02/2017 11:30 AM									
Facility Rep								epresentativ	es						
On-Site	On-Site Representative(s)Title, Phone Number						Responsible Official(s), Title, Phone Number								
Statute and Section Information															
Federal	Statute:	CWA - 0	Ilean Water	Act			State Statute: Tennessee Water Qual						uality Control Act		
Programs: NPDES-Stormwater Construction															
Compliance Monitoring Reason: Core Program															
Compliance Monitoring Agency Type: State Agency Name: TDEC - DWR															
Did EPA assist/ Inspection?						Time Physically conducting activity: Days: 1							Hours:		
Inspection Type: State					Compliance Monitoring Action Outcome: No N						lo Violation				
Lead Agency: State					Compliance Monitoring Rating Code: Unra						nrated				
If Joint Inspection, what was the purpose of the other party?															
	MA THE STATE OF TH		Areas E	valuat	ed Dur	ing l	nspecti	on (Check on	ly those	areas e	valu	ated)			
⊠ Pe	ermit					Self - Compliance Program				Pretreatment					
⊠ R	□ Records / Records □					Compliance Schedule					Pollution Prevention				
☐ Fa	Facility Site Review					Laboratory				\boxtimes	Storm Water				
E1	Effluent / Receiving Waters					Operations & Maintenance					Combined Sewer Overflow				
☐ Flow Measurement ☐						Sludge Handling / Disposal					Sanitary Sewer Overflow				
Compliance Monitoring Summary															
Site has minor EPSC repairs needed and minor paperwork deficiencies.															
EPA and State Representatives															
Jeann Wills						DWR/NEFO/615-687-7024						3/9///7			
Inspector's Signature					Agency / Office / Phone						Date				
agrie Briggie					DWR/NEFO/615-687-7018						3/24/17				
Manager's Signature					Agency / Office / Phone						Date				



TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243 1-888-891-8332 (TDEC)

Compliance Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

				unter Photos				NPD	ES Tracking	Number	TNR149909	
Site	e/Project Name:	Terrabi	ooke Development						Coverage wa	18-MAY-15		
Street Address or							date:	01-OCT-14				
	eet Address or cation:	9655 Sp	lit Log Road						nated end da	23-MAY-16		
			ation and dayslonman	ial ed i	including		Latitude (dd.dddd): 35.9521					
Site	e scription:		n 8-lot residential sd including ds, and home building				Longitude (-dd.dddd):					
DU	, criptioni								Acres Disturbed: 8			
County(ies): Williamson EFO: Nashville				MS4 Jurisdiction:				Total Acres:				
NI.	of Dougelittee (T) areal an are	Operator): Split Log	Davelonment	LLC							
				1						C t t Pl	(15 (20 71(2	
Name of Official Contact: James Carbine Email: jca						arbine	ecompany.c	com			ne: 615-620-7162	
Address: 621 Bradley Ct. City: Fran									State: TN Zip: 370			
Che	ck List (office & fie				Yes	No			Comments			
1	Does the site hav		verage?		X							
2	Is NOC posted or					M						
3	Have the site con	tractors si	gned the NOI?		Ø							
4	Is the current SW			\boxtimes								
5	Are EPSCs in acc		X									
6	Are EPSCs instal											
7	Are inspection re		\boxtimes									
8	Is the proper buff		X									
Were there unstable, inactive areas on the site? If so, does						Ø						
				ne has been more than 14 days								
_	(or 7 days for ste			X								
10	Are more than 50		+=									
11						X						
12						X						
13						X						
14	14 Are there violations of an existing ARAP? If so, ARAP No.?					$ \boxtimes$						
15 Other pollutants/discharges or unusual problems?						X						
Project is complete and stable with no construction-related stormwater discharges?						Ø						
Go	neral Comments:	<u>6</u> • 5 •										
1	NIMOR EPS (- Mpa	irs reeded.									
		,										
		,		- 1			Tel					
Routine Comprehensive Complaint Follow Up Termination												
On-Site Contact (if available)							1	Signature:			Date:	
On-Site Contact Name (Print): On-Site Contact Title				tact litte:	itie:			oignature.			Date.	
TD	EC Personnel/Infor	mation									and Address	
Inspector's Name (Print): Signature:								Date: 3/2//	7 Na	mental Field Office		
1 -1 -1 -1					1-			Time: \\\ 5	/ 11 R.O. Olass Bodi			
Leanna Cittler flamme					allo			11ms: 1112	1110			

Project Name: TNR149909 **Location**: 9655 Split Log Road

Date: 03/02/2017 Inspector: LNL







Buffer zone maintained

